



Exam Code: 920-443

Exam Name: nncse-succession 1000/1000m rls.3.0

Vendor: Nortel

Version: DEMO

Part: A

1: A multi-site Succession 1000/1000M RIs 3.0 system has just been networked to a third-party H.323 Gateway via IP Peer Networking. During call testing, it was discovered that NO Succession telephone calls can be completed to this third-party Gateway. Which three actions will determine the root cause or lead to the resolution of this call issue? (Choose three.)

A. Verify the data network integrity to the third-party Gateway.

B. Verify that the H.323 Signaling Gateways in both systems are running and registered with their appropriate H.323 Gatekeeper.

C. Verify that the telephone(s) used for testing are compatible with this Gateway. If NOT, change to a H.323 compatible telephone.

D. Verify that the H.323 Signaling Gateway application is installed and running on the Signaling Server in this system and in the third-party system.

ERROR: undefined
OFFENDING COMMAND: mFSF2S58YFFFFFFFA8

STACK:

[88.309 0 0 -88 0 0]
-dictionary-
/F2S58YFFFFFFFA8